

ABSTRACT
A major landslide occurred on the south side of Cotton Brook in the Mt. Mansfield State Forest in May 2019. The immediate goals of the Vermont Geological Survey were to 1) document threats in the area, 2) characterize the site, 3) propose approximate "exclusion areas" for trails, and 4) collect baseline data so we can evaluate impacts and change.

The area of the landslide is approximately 12 acres. The landslide resulted in massive sedimentation in Cotton Brook and a large delta in the Waterbury Reservoir. A comparison of elevation data from the VTRANS drone flights on June 12 with the pre-landslide Lidar data shows approximately 200,000 cubic meters of material was excavated, 100,000 cubic meters was deposited at the base, 25,000 cubic meters are estimated in the delta, and 75,000 cubic meters remain unaccounted for (deposited along the brook, in the reservoir, or transported down the Little River). The landslide blocked Cotton Brook, leading to an impoundment upstream. Fractures formed on the wooded hillsides adjacent to the landslide scar and these are areas of potential failure.

The slope, roughly 25 degrees, is composed of fine silt and sand lake bottom sediments deposited in Glacial Lake Winooski (Wright, 2019). A slide surface of very fine silt to clay is visible and has been grooved and striated by the overriding material. Mud flows on the surface, fallen trees and boulders, new cracks on the Foster's Trail, and undercutting of the landslide material by the brook along its new channel all contribute to the site remaining hazardous and impacting water quality nearly 5 months later.

Saturation of unconsolidated material above the impermeable clay-silt layer (s), dipping slide surface, type of material (sand over clay), height (109 m), load balance, gravity, and steepness of slope are all likely factors influencing the mass failure; the causes are under investigation.

Although changes in frequency of landslides can be an indicator of climate change, we do not have many accurate historical records for landslides in Vermont. However, the Vermont Geological Survey's landslide inventory contains nearly 2000 points and will serve as a baseline going forward.




Fig 1. June 12, 2019: Drone flight by VTRANS showed 12 acres active plus 2.2 acres detached along the margins. ~100,000 cubic meters of material is in the toe deposit.



Fig. 2. June 12, 2019: Ground cracks and scarps due to rotational failure along landslide margins. Foster's Trail ended abruptly.



Fig 3. June 12, 2019: Downstream, a new delta formed in the Waterbury reservoir. The delta was ~2.8 acres.



Landslide Inventory of Vermont, 2019
The inventory includes over 2100 sites. We have completed the inventory of existing and historic sites Addison, Chittenden, Washington and Orange counties. We also capture sites from the on-line reporter and other verified reports in Vermont.

Foster's Trail Landslide

Due to an active landslide occurring on the Foster's Trail the following sections of trail will be closed until further notice:

- Foster's Trail
- Cotton Brook Road from the hay shed to Kelty Corners (see map). Trail use can occur between the Cotton Brook Road gate and the hay shed.

The landslide is still active.
FOR YOUR SAFETY DO NOT ENTER THE CLOSED AREAS

Above: The Dept. of Forests, Parks and Recreation posted signage which informs the public about the danger of the active site.
Below: Location and cumulative precipitation.



Fig. 4. October 8, 2019: View of the impoundment and the toe deposit. The pond extended upstream and encompassed approximately 1.8 acres.



Fig. 5. June 4, 2019: Grooved, striated slip surface beneath sands, silt and debris near the base of the slope. No bedrock was exposed.



Fig. 6. June 4, 2019: Mudflows, saturated sand, boulders and trees indicated the site was still active. Water feeding the mudflows was from seeps partway down the slope, likely at a sand-silt interface or due to elevated water table.

Landslide Inventory Attributes

| ACTIVITY | AREA ESTIMATE | ASPECT | BANK POSITION | BEDROCK CONTROL | BEDROCK ON SLOPE |
|------------------|------------------|------------------|---------------|-----------------|------------------|
| Text | Text | Text | Text | Text | Text |
| CAUSE 1 | CAUSE 2 | COMMENTS | CREATE DATE | CREATOR | CROWN ELEVATION |
| Text | Text | Text | Date or Time | Text | Number |
| FAIL DATE | FAIL DATE | FAIL DATE | FAIL DATE | FIELD VISIT | HEAD CUTS |
| Date or Time | Date or Time | Date or Time | Date or Time | Text | Text |
| LANDSLIDE TYPE 1 | LANDSLIDE TYPE 2 | LENGTH (METERS) | MATERIAL | OBSERVER | ORGANIZATION |
| Text | Text | Text | Text | Text | Text |
| OUTSIDE MEANDER | PIPING | REMEDIATED | SEEPS | SLIDE ANGLE | SLOPE ANGLE |
| Text | Text | Text | Text | Text | Text |
| SOURCE PUB DATE | SPRINGS | SUBP OBSERVATION | TALUS | TOE CONDITION | TOWN |
| Text | Text | Text | Text | Text | Text |
| | | | | | VISIT DATE |
| | | | | | Date or Time |

Two Common Types of Landslides in Vermont: a) rotational slump and flow, b) translational slide and flow. From Highland and Bobrowsky (2008).

